



MOTOAMERICA TECHNICAL BULLETIN

03-2018

Provisional Rule Change Stock 1000

Technical bulletin 03-2018 Provisional rule change Stock 1000

There is a misprint in the provisional rules section 2.6.10.3/e. stating the triple clamps may be modified. This section has been changed to triple clamps must remain as homologated.

Please contact technicaldirector@motoamerica.com with any questions. We apologize for any inconvenience this may have caused.

