

The following updates have been made to the technical rules.

Section 2.4.8.14/ 2.5.8.14/ 2.6.8.14/ 2.8.8.14 Oil Lines

Oil lines may be modified or replaced. Oil lines containing positive pressure, if replaced, must be of ~~metal~~ **braided** reinforced construction with swaged or treaded connectors. *Oil lines do not need to be of metal construction but must have a braided reinforcement.*

Section 2.8.8.13 Clutch

Removed: d. ~~The clutch basket (outer) must be the originally fitted and homologated part but may be reinforced.~~
Altered: e. **The original clutch assembly (including the clutch basket) may be modified or replaced by an aftermarket unit. The maximum retail price of the complete assembly is \$1200. The clutch may include back torque limiting capabilities (slipper type).**

Twins Homologation

2018 Yamaha XSR700 is added to the pending homologation list.

Please contact technicaldirector@motoamerica.com with any questions



MOTOAMERICA TECHNICAL BULLETIN

01-2018

