

2021 Parc Fermé Inspection Summary

Round 1 Road Atlanta

SBK #	Inspection:	Result:	SSP #	Inspection:	Result:	JRC #	Inspection:	Result:	TWN #	Inspection:	Result:	STKIK #	Inspection:	Result:	BAG #	Inspection:	Result:
Q1	76 Missing proper oil fill safety wire	FAIL	Q1	68 Missing rear safety light	FAIL	Q1	58 Missing rear safety light	FAIL	Q1	310 Missing brake caliper safety wire	FAIL	Q1	42 Missing rear safety light	FAIL	Q1	48 Missing brake caliper safety wire	FAIL
R1	2 Chassis Weight	PASS	Q1	33 Missing rear safety light	FAIL	Q2	22 Missing proper oil fill safety wire	FAIL	Q1	310 Missing rear tire sticker	FAIL	Q1	94 Missing proper oil fill safety wire	FAIL	Q1	29 Missing rear safety light	FAIL
R1	11 Chassis Weight	PASS	Q2	68 Non-homologated camera installed	FAIL	Q1	75 Missing rear safety light	FAIL	Q1	200 Missing rear safety light	FAIL	Q1	79 Missing brake caliper safety wire	FAIL	Q1	34 Missing rear safety light	FAIL
R1	50 Chassis Weight	PASS	Q2	99 Additive in cooling system	FAIL	R1	15 Non-homologated rear swingarm pivot bolt	FAIL	Q2	52 Missing brake caliper safety wire	FAIL	Q1	79 Missing rear tire sticker	FAIL	R1	79 Chassis Weight	PASS
R1	94 Chassis Weight	PASS	R1	33 Missing tire stickers	FAIL	R1	22 Missing proper oil fill safety wire	FAIL	R1	128 Rear brake caliper missing	FAIL	Q1	27 Missing brake caliper safety wire	FAIL	R1	29 Chassis Weight	PASS
			R1	59 Missing tire stickers	FAIL	R1	29 Chassis combined Weight	PASS	R1	270 Missing tire stickers	FAIL	Q1	27 Non-homologated cam chain tensioner	FAIL	R1	48 Chassis Weight	PASS
			R1	1 Chassis Weight	PASS	R1	96 Chassis combined Weight	PASS	R1	190 Missing proper oil fill safety wire	FAIL	Q1	48 Modified rear shock linkage	FAIL	R1	15 Chassis Weight	PASS
			R1	40 Chassis Weight	PASS	R1	29 Airbox inspection	PASS	R1	227 Missing tire stickers	FAIL	Q1	99 Modified rear shock linkage	FAIL	R1	13 Chassis Weight	PASS
			R1	52 Chassis Weight	PASS	R1	70 Chassis combined Weight	PASS	R1	377 Missing tire stickers	FAIL	Q2	22 Missing brake lever guard	FAIL	R1	14 Chassis Weight	PASS
			R2	24 Missing proper oil dipstick safety wire	FAIL	R1	34 Chassis combined Weight	PASS	R1	49 Chassis Weight	PASS	Q2	192 Missing brake reservoir cover	FAIL			
			R2	99 Missing tire stickers	FAIL				R1	51 Chassis Weight	PASS	Q2	124 Non-homologated cam chain tensioner	FAIL			
			R2	48 Non-homologated front forks	FAIL				R1	270 Chassis Weight	PASS	Q2	42 Missing rear safety light	FAIL			
			R2	1 Rear shock teardown	FAIL				R1	717 Chassis Weight	PASS	Q2	41 Non-homologated tank cover	FAIL			
			R2	60 Rear shock teardown	FAIL				R1	42 Missing brake caliper safety wire	FAIL	R1	42 Missing rear safety light	FAIL			
			R2	97 Rear shock teardown	FAIL				R1	10 Chassis Weight	PASS	R1	55 Chassis Weight	PASS			
									R1	99 Chassis Weight	PASS	R2	71 Modified upper triple	FAIL			
									R2	71 Additive in cooling system	FAIL	R2	71 Additive in cooling system	FAIL			
									R2	124 Modified upper triple	FAIL	R2	124 Modified upper triple	FAIL			
									R2	124 Non-homologated cam chain tensioner	FAIL						

Round 2 Virginia

SBK #	Inspection:	Result:	SSP #	Inspection:	Result:	JRC #	Inspection:	Result:	TWN #	Inspection:	Result:	STKIK #	Inspection:	Result:	BAG #	Inspection:	Result:
Q2	11 Chassis Weight	PASS	Q1	24 Non-homologated tank cover	FAIL	Q1	55 Illegal air deflector	FAIL	Q1	996 Missing tire stickers	FAIL	Q1	518 Non-homologated rear axle adjusters	FAIL			
Q2	32 Chassis Weight	PASS	Q1	11 Missing tail and lower bodywork pieces	FAIL	Q2	29 Chassis combined Weight	PASS	Q2	43 Missing brake lever guard	FAIL	Q1	298 Missing side and lower bodywork pieces	FAIL			
Q2	33 Chassis Weight	PASS	Q1	93 Missing proper oil dipstick safety wire	FAIL	Q2	12 Chassis combined Weight	PASS	R1	18 Missing MotoAmerica and Dunlop Logos	FAIL	Q1	562 Missing brake caliper safety wire	FAIL			
Q2	45 Chassis Weight	PASS	Q1	93 Missing brake caliper safety wire	FAIL	Q2	93 Chassis combined Weight	PASS	R1	227 Missing Dunlop logos on fender	FAIL	Q1	13 Non-homologated rear swimarm damper	FAIL			
Q2	76 Chassis Weight	PASS	Q2	1 Non-homologated farina stav	FAIL	Q2	62 Chassis combined Weight	PASS	R1	136 Missing Dunlop logos on fender	FAIL	Q2	562 Illegal swimarm cover	FAIL			
R1	88 Missing front tire sticker	FAIL	Q2	90 Non-homologated farina stav	FAIL	Q2	93 Chassis combined Weight	PASS	R1	16 Missing Dunlop logos on fender	FAIL	Q2	562 Missing tire guard	FAIL			
			R1	97 Misfire MotoAmerica Logo	FAIL	R1	29 Airbox inspection	PASS	R1	219 Missing Dunlop logos on fender	FAIL	Q2	43 Non-homologated brake pistons	FAIL			
			R1	60 Missing rear tire sticker	FAIL	R1	70 Airbox inspection	PASS	R1	37 Missing Dunlop logos on fender	FAIL	Q2	124 Non-homologated brake pistons	FAIL			
			R2			R2	62 Missing tire stickers	FAIL	R1	717 Missing Dunlop logos on fender	FAIL	R1	108 Missing MotoAmerica Logo	FAIL			
			R2			R2	29 Missing brake caliper safety wire	FAIL	R2			R1	43 Missing MotoAmerica Logo	FAIL			
			R2			R2	34 Missing MotoAmerica and Dunlop Logos	FAIL	R2			R2	22 Airbox inspection	FAIL			
			R2			R2	99 Missing Dunlop logos on fender	FAIL	R2			R2	85 Airbox inspection	FAIL			
			R2			R2	14 Missing Dunlop logos on fender	FAIL	R2			R2	99 Airbox inspection	PASS			
			R2			R2	69 Missing Dunlop logos on fender	FAIL	R2			R2	23 Airbox inspection	PASS			
			R2			R2	29 Missing MotoAmerica Logo	FAIL	R2			R2	55 Airbox inspection	PASS			
			R2			R2	58 Missing MotoAmerica Logo	FAIL	R2			R2	227 Missing tire stickers	FAIL			
									R2		R2	164 Missing tire stickers	FAIL				
									R2		R2	175 Missing tire stickers	FAIL				
									R2		R2	55 Missing oil fill safety wire	FAIL				
									R2		R2	55 Missing brake caliper safety wire	FAIL				

Round 3 Road America

SBK #	Inspection:	Result:	SSP #	Inspection:	Result:	JRC #	Inspection:	Result:	TWN #	Inspection:	Result:	STKIK #	Inspection:	Result:	BAG #	Inspection:	Result:	
Q2	2 Chassis combined Weight	PASS	Q1	53 Non-homologated rear brake actuator	FAIL	Q1	99 Missing brake caliper safety wire	FAIL	R1	896 Missing oil fill safety wire	FAIL	Q1	87 Missing tire stickers	FAIL				
Q2	33 Chassis combined Weight	PASS	Q1	59 Illegal modification to rear suspension link	FAIL	Q1	98 Ineffective Quickshift Module	FAIL	R1	112 Missing rear safety light	FAIL	Q1	124 Additive in cooling system	FAIL				
Q2	33 Chassis combined Weight	PASS	Q1	16 Illegal modification to rear suspension link	FAIL	Q2	12 Chassis combined Weight	PASS	R1	112 Missing rear safety light	FAIL	Q1	124 Additive in cooling system	FAIL				
Q2	45 Chassis combined Weight	PASS	Q1	85 Illegal cross-homologation of rear link	FAIL	Q2	22 Chassis combined Weight	PASS	R1			Q1	26 Missing front fender	FAIL				
Q2	50 Chassis combined Weight	PASS	Q1	85 Illegal modification to upper triple	FAIL	Q2	70 Chassis combined Weight	PASS	R1			R1	73 Not present in parc ferme	FAIL				
Q2	70 Chassis combined Weight	PASS	Q1	85 Missing side bodywork on tank	FAIL	Q2	70 Chassis combined Weight	PASS										
Q2	80 Chassis combined Weight	PASS	R1	12 Missing tire stickers	FAIL	R1	93 Chassis combined Weight	PASS										
R1	26 Missing brake caliper safety wire	FAIL	R2	1 Chassis combined Weight	PASS	R2	99 Modified rear suspension link	FAIL										
			R2	37 Chassis combined Weight	PASS	R2	40 Chassis combined Weight	PASS										
			R2	80 Chassis combined Weight	PASS	R1	53 Missing tire stickers	FAIL										
			R2	38 Missing tire stickers	FAIL													
			R2	53 Missing tire stickers	FAIL													

Round 4 The Ridge

SBK #	Inspection:	Result:	SSP #	Inspection:	Result:	JRC #	Inspection:	Result:	TWN #	Inspection:	Result:	STKIK #	Inspection:	Result:	BAG #	Inspection:	Result:
Q1	95 Additive in cooling system	FAIL	Q1	57 Non-homologated brake pistons	FAIL	Q1	69 Missing brake caliper safety wire	FAIL	Q1	18 Missing proper oil fill safety wire	FAIL	Q1	960 Non-homologated brake pistons	FAIL			
Q1	90 Not present in parc ferme	FAIL	Q1	97 Missing MotoAmerica Logo	FAIL	Q2	15 Additive in cooling system	FAIL	Q1	17 Missing brake caliper safety wire	FAIL	Q1	75 Additive in cooling system	FAIL			
			Q1	64 Missing brake caliper safety wire	FAIL				Q1	128 Missing proper oil fill safety wire	FAIL	Q1	59 Missing Dunlop logos on fender	FAIL			
			Q1	93 Missing brake caliper safety wire	FAIL				Q1	192 Non-allocated tire compound	FAIL	Q1	131 Illegal Dunlop logos	FAIL			
			Q2	57 Missing tire stickers	FAIL				Q1	270 Non-allocated tire compound	FAIL	Q2	99 Non-homologated cam chain tensioner	FAIL			
			Q2	69 Missing side bodywork on tank	FAIL				Q1	717 Missing brake caliper safety wire	FAIL	Q2	124 Illegal adjustable swing arm pivot	FAIL			
			Q2	97 Missing oil fill safety wire	FAIL				Q2	60 Additive in cooling system	FAIL	Q2	42 Missing oil fill safety wire	FAIL			
			R1	97 Missing brake caliper safety wire	FAIL				R2	717 Missing brake lever guard	FAIL	R1	55 Missing proper oil fill safety wire	FAIL			
			R1	45 Missing brake caliper safety wire	FAIL				R2			R1	69 Missing brake caliper safety wire	FAIL			
									R2		R2	79 Missing brake caliper safety wire	FAIL				

Round 5 Laguna Seca

SBK #	Inspection:	Result:	SSP #	Inspection:	Result:	JRC #	Inspection:	Result:	TWN #	Inspection:	Result:	STKIK #	Inspection:	Result:	BAG #	Inspection:	Result:
Q1	24 Missing Dunlop logos on fender	FAIL	Q1	58 Missing side bodywork on tank	FAIL	Q1	25 Missing side bodywork on tank	FAIL	P1	52 Missing tire stickers	FAIL	Q1	164 Missing tire stickers	FAIL	Q1	29 Non-allocated tire compound	FAIL
Q2	88 Missing tire stickers	FAIL	Q1	81 Missing side bodywork on tank	FAIL	Q1	25 Non-functioning quickshift module	FAIL	Q1	49 Missing tire stickers	FAIL	Q1	71 Forfeited tires, removed from parc ferme	FAIL	Q1	33 Chassis combined Weight	PASS
R1	24 Missing Dunlop logos on fender	FAIL	Q2	15 Missing rear safety light	FAIL	Q1	25 Illegal Engine - Incorrect head gasket configuration	FAIL	Q2	111 Missing rear safety light	FAIL	Q1	134 Illegal suspension linkage modification	FAIL	Q2	34 Chassis combined Weight	PASS
			Q2	80 Missing brake caliper safety wire	FAIL	Q2	29 Chassis combined Weight	PASS	Q2	192 Missing rear safety light	FAIL	Q1	161 Illegal suspension linkage modification	FAIL	Q2	44 Chassis combined Weight	PASS
			Q2	80 Missing Dunlop logos on fender	FAIL	Q2	34 Chassis combined Weight	PASS	R1	192 Missing tire stickers	FAIL	Q1	111 Missing proper oil fill safety wire	FAIL	Q2	87 Chassis combined Weight	PASS
			R1	15 Missing tire stickers	FAIL	Q2	48 Chassis combined Weight	PASS	R1			Q1	153 Missing proper oil fill safety wire	FAIL	R1	29 Chassis combined Weight	PASS
			R1	1 Airbox inspection	PASS	Q2	73 Chassis combined Weight	PASS	R1			Q2	125 Missing brake caliper safety wire	FAIL	R1	33 Chassis combined Weight	PASS
			R2	28 Airbox inspection	PASS	Q2	70 Chassis combined Weight	PASS	R2			Q2	990 Missing tire stickers	FAIL	R1	34 Chassis combined Weight	PASS
			R2	40 Airbox inspection	PASS	Q2	10 Missing brake caliper safety wire	FAIL	R2			Q2	765 Modified upper triple clamp	FAIL			
			R2	88 Airbox inspection	PASS	R1	69 Missing tire stickers	FAIL	R2			R1	42 Illegal bolt material on front calipers	FAIL			
			R2			R2	25 Illegal Engine configuration - results removed for the weekend	FAIL	R2			R1	70 Illegal bolt material on front calipers	FAIL			
			R2			R2	29 Airbox inspection	PASS	R2			R1	73 Illegal bolt material on front calipers	FAIL			
			R2			R2	70 Airbox inspection	PASS	R2			R1	74 Illegal bolt material on front calipers	FAIL			
			R2			R2	72 Airbox inspection	PASS	R2			R1	518 Illegal bolt material on front calipers	FAIL			
			R2			R2	70 Engine sealed for future inspection	PASS	R2			R1	765 Illegal bolt material on front calipers	FAIL			

Round 6 Brainerd

SBK #	Inspection:	Result:	SSP #	Inspection:	Result:	JRC #	Inspection:	Result:	TWN #	Inspection:	Result:	STKIK #	Inspection:	Result:	BAG #	Inspection:	Result:
Q1	59 Left unsecured fuel	FAIL	Q1	20 Engine teardown inspection	FAIL	Q1	20 Engine teardown inspection	FAIL	Q1	959 Additive in cooling system	FAIL	Q1	139 Additive in cooling system				