





Round 8 COTA																			
SBK	#	Inspection:	Result:	SSP	#	Inspection:	Result:	STK1K	#	Inspection:	Result:	BAG	#	Inspection:	Result:	RSD	#	Inspection:	Result:
R2	1	Chassis weight	PASS	Q1	85	Illegal rear brake mounting	FAIL	Q1	87	Missing brake caliper safety wire - rear	FAIL	Q1	17	Illegal rear tire	FAIL	P1	93	Late to weekend tech inspection	FAIL
R2	1	Fuel sample analysis	FAIL	Q1	94	Missing brake caliper safety wire - rear	FAIL	Q1	111	Improper oil fill safety wire	FAIL	Q1	87	Missing rain light	FAIL	Q1	126	Missing rain light	FAIL
R2	2	Chassis weight	PASS	Q1	94	Additive in cooling system	FAIL	R2	174	Missing tire stickers, installed in parc ferme	FAIL	Q2	1	Bike not present in parc ferme	FAIL	Q1	407	Missing rain light	FAIL
R2	2	Fuel sample analysis	PASS	Q1	94	Master brake cylinder not on approved parts list	FAIL	R2	10	Airbox inspection	PASS	Q2	10	Chassis weight	PASS	Q1	408	Missing rain light	FAIL
R2	50	Chassis weight	PASS	Q1	95	Illegal fuel tank cover	FAIL	R2	51	Airbox inspection	PASS	Q2	33	Chassis weight	PASS	Q2	519	Bike not present in parc ferme	FAIL
R2	96	Chassis weight	PASS	Q2	4	Chassis Combined Weight	PASS	R2	69	Airbox inspection	PASS	Q2	43	Chassis weight	PASS	Q2	6	Missing brake caliper safety wire - rear	FAIL
R2	99	Chassis weight	PASS	Q2	12	Chassis Combined Weight	PASS	R2	71	Airbox inspection	PASS	Q2	50	Chassis weight	PASS	R1	37	Illegal frame	FAIL
R2	99	Fuel sample analysis	PASS	Q2	14	Chassis Combined Weight	FAIL	R2	76	Airbox inspection	PASS								
				Q2	70	Chassis Combined Weight	PASS	R2	78	Airbox inspection	PASS								
				Q2	79	Chassis Combined Weight	PASS												
				Q2	85	Chassis Combined Weight	PASS												

Round 9 New Jersey																			
SBK	#	Inspection:	Result:	SSP	#	Inspection:	Result:	JRC	#	Inspection:	Result:	TWN	#	Inspection:	Result:	BAG	#	Inspection:	Result:
Q1	1	Chassis weight	PASS	Q1	4	Chassis Combined Weight	PASS	P1	62	Late to weekend tech inspection	FAIL	Q2	27	Bike removed from parc ferme	FAIL	Q1	1	Chassis weight	PASS
Q1	2	Chassis weight	PASS	Q1	23	Chassis Combined Weight	PASS	Q2	96	Drain plug from wet session removed in parc ferme	FAIL	Q1	10	Chassis weight	PASS	Q1	10	Chassis weight	PASS
Q1	11	Chassis weight	PASS	Q1	52	Chassis Combined Weight	PASS	Q1	34	Chassis Combined Weight	PASS	Q1	33	Chassis weight	PASS	Q1	43	Chassis weight	PASS
Q1	50	Chassis weight	PASS	Q1	70	Chassis Combined Weight	PASS	Q1	48	Chassis Combined Weight	PASS	Q1	43	Chassis weight	PASS	Q1	79	Chassis weight	PASS
Q1	99	Chassis weight	PASS	Q1	85	Chassis Combined Weight	PASS	Q1	70	Chassis Combined Weight	PASS	Q1	1	Bike removed from parc ferme	FAIL				
				Q2	85	Tire stickers installed in parc ferme	FAIL	Q1	92	Chassis Combined Weight	PASS	Q2	1						
								Q1	99	Chassis Combined Weight	PASS	Q2	96	Drain plug from wet session removed in parc ferme	FAIL				
								R1	11	Restrictor plate inspection	PASS	R1	11	Restrictor plate inspection	PASS				
								R1	13	Restrictor plate inspection	PASS	R1	13	Restrictor plate inspection	PASS				
								R1	39	Restrictor plate inspection	PASS	R1	39	Restrictor plate inspection	PASS				
								R1	76	Restrictor plate inspection	PASS	R1	76	Restrictor plate inspection	PASS				
								R1	92	Restrictor plate inspection	PASS	R1	92	Restrictor plate inspection	PASS				
								R2	54	Rain plug not removed for wet race	FAIL	R2	54	Rain plug not removed for wet race	FAIL				
								R2	13	Engine teardown inspection	PASS	R2	13	Engine teardown inspection	PASS				
								R2	14	Engine teardown inspection	FAIL	R2	14	Engine teardown inspection	FAIL				
								R2	39	Engine teardown inspection	PASS	R2	39	Engine teardown inspection	PASS				
								R2	48	Engine teardown inspection	PASS	R2	48	Engine teardown inspection	PASS				
								R2	71	Engine teardown inspection	PASS	R2	71	Engine teardown inspection	PASS				

2023 SEASON TOTALS	
PASS	354
FAIL	123
TOTAL	477

2022 SEASON TOTALS	
PASS	277
FAIL	158
TOTAL	435

2021 SEASON TOTALS	
PASS	179
FAIL	265
TOTAL	444

2020 SEASON TOTALS	
PASS	161
FAIL	173
TOTAL	334

2019 SEASON TOTALS	
PASS	168
FAIL	110
TOTAL	278