

Round 3 Road America

SBK	#	Inspection:	Result:	SSP	#	Inspection:	Result:	JRC	#	Inspection:	Result:	STK1K	#	Inspection:	Result:	BAG	#	Inspection:	Result:
Pre	54	Engine teardown inspection - cam box area, cam caps, Transmission gear ratio, pistons, connecting rods.	PASS	Q1	27	Missing brake caliper safety wire - rear	FAIL	Pre	48	Engine inspection - Woodruff key	PASS	P1	90	No functioning transponder	FAIL	Q2	1	Chassis weight	PASS
Q1	22	Bike not present in parc ferme	FAIL	Q1	78	Missing brake caliper safety wire - rear	FAIL	Pre	69	Engine inspection - Woodruff key	PASS	Q1	31	Master brake cylinder not on approved parts list	FAIL	Q2	10	Chassis weight	PASS
R1	25	Data downloaded prior to completion of parc ferme	FAIL	Q2	4	Chassis Combined Weight	PASS	Pre	71	Engine inspection - Woodruff key	PASS	Q1	79	Missing chain guard and shark fin	FAIL	Q2	33	Chassis weight	PASS
R1	45	Chassis weight	PASS	Q2	12	Chassis Combined Weight	PASS	Pre	99	Engine inspection - Woodruff key	PASS	Q2	79	Missing brake caliper safety wire - all	FAIL	Q2	43	Chassis weight	PASS
R1	54	Chassis weight	PASS	Q2	20	Chassis Combined Weight	PASS	Q1	34	Chassis Combined Weight	PASS	R1	174	Tire stickers installed in parc ferme	FAIL	Q2	79	Chassis weight	PASS
				Q2	36	Chassis Combined Weight	PASS	Q1	48	Chassis Combined Weight	PASS	R2	10	Airbox and throttle body inspection	PASS	Q2	88	Chassis weight	FAIL
				Q2	37	Chassis Combined Weight	PASS	Q1	69	Chassis Combined Weight	PASS	R2	16	Airbox and throttle body inspection	PASS				
				Q2	43	Chassis Combined Weight	PASS	Q1	71	Chassis Combined Weight	PASS	R2	47	Airbox and throttle body inspection	PASS				
				Q2	70	Chassis Combined Weight	PASS	Q1	99	Chassis Combined Weight	PASS	R2	47	Airbox and throttle body inspection	PASS				
				Q2	96	Chassis Combined Weight	PASS	Q2	23	Missing brake caliper safety wire - front	FAIL	R2	51	Airbox and throttle body inspection	PASS				
								Q2	32	Non-MotoAmerica camera found on machine	FAIL	R2	69	Airbox and throttle body inspection	PASS				
								R1	13	Engine sealed for future inspection	PASS								
								R1	34	Engine sealed for future inspection	PASS								
								R1	48	Engine sealed for future inspection	PASS								
								R1	69	Engine sealed for future inspection	PASS								
								R1	71	Engine sealed for future inspection	PASS								
								R1	99	Engine sealed for future inspection	PASS								
								R2	34	Tire stickers installed in parc ferme	FAIL								
								R2	13	Chassis Combined Weight	PASS								
								R2	14	Engine sealed for future inspection	PASS								
								R2	34	Chassis Combined Weight	PASS								
								R2	39	Engine sealed for future inspection	PASS								
								R2	48	Chassis Combined Weight	PASS								
								R2	69	Chassis Combined Weight	PASS								
								R2	71	Chassis Combined Weight	PASS								
								R2	99	Chassis Combined Weight	PASS								

SEASON TOTALS	
PASS	177
FAIL	63
TOTAL	240